

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N M. R. 23W


Marquette COUNTY

DESCRIPTION OF CORNER 4 Corner bet. Secs. 17-18

CORNER MONUMENT 1 1/2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 4-11-67

WITNESSES TO CORNER..... 9" Cedar (NBT) N66°E 35.4'



7" Soft Maple (NBT) S42°E 14.5'

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

Corner lies 12' east of old road bed and 45' east of  
LC present county road.

Found iron pipe as recorded 1933. Location checks with old  
road location and buildings as noted.

**SURVEYOR'S SEAL**

SIGNED *Silly O. Buckler* DATE \_\_\_\_\_  
REGISTERED LAND SURVEYOR