

REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/18, 199 7

Mike Sanki 265
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE
(County)

Located In: Corner Code #

1. Public Land Survey	T <u>34</u> N R <u>27</u> W	I-09
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

RECORDED FOR RECORD
97 DEC 22 AM 11:27
REGISTER OF DEEDS
585 BKS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on Mar. 04, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5			4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Sugar, 10" - S35°W - 11 lks.; Hemlock, 10" - N65°W - 39 lks. All original evidence for this corner has been destroyed by county road improvements and logging activities.
- 1900: Subdivision of Section 22 by Albert Hass states 4" Cedar Post in Road - Nothing near.
- 1977: L.C.R.C. No. 175 by G.B. Wilson states set 4" square conc. mon. 207' West of Centerline of RR per 1877 Railroad Survey Map - checks with Albert Hass survey. TIES: Oak, 5" - N80°W - 34.4'; Oak, 2" - N18°W - 23.1'; Oak, 1" - N40°E - 17.5'; Stump - N58°W - 20.2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 4 inch square concrete monument 207 feet West of the centerline of the Chicago and Northwestern Railroad per L.C.R.C. NO. 175. As stated in Wilson's record, this position fits closely with measurements shown in Albert Hass' Survey, and is accepted as the best available evidence of the position of the original corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 4" square concrete monument - Set 3-1/4" Alum cap stamped for corner position on monument:

8" dia. Oak	N31°E	42.01 feet	Scr. NBT
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 1' NW of P.P.	S54°E	78.43 feet	
20" dia. Maple	S35°W	36.30 feet	Scr. NBT
18" dia. Maple	N59°W	30.42 feet	Scr. NBT
Survey Sign Post	North	4.9 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Oct. 24, 1997

585