

SURVEY &  
REMONUMENTATION

LIBER 15292 PG 365

MAR 15 95 04 1977

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

OK - T. SMITH

For corners in  
OAKLAND COMMISSION  
(County)

Located In: WATERFORD Corner Code #

- 1. Public Land Survey T 3 N R 9 E J-5  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
- 2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
- 3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

\$ 7.00 MISC RECORDING CHG - IN HOUSE  
\$ 2.00 REMON CHG - IN HOUSE  
15 MAR 95 8:08 A.M. RECEIPT# 88  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS  
Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-30-94  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5									●				
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, THOMAS M. SMITH, in a field survey on NOVEMBER 24, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

POST, G.L.O. 1" IRON  
1817 L.C.R.C.  
L. 5758 P. 010  
CUMBERWORTH, 1971

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I FOUND A 1" IRON PIPE IN A GRASS AREA JUST SOUTH OF SAGINAW TRAIL ROAD. I VERIFIED CORNER POSITION FROM THE CUMBERWORTH WITNESSES. I ALSO VERIFIED CORNER WITH THE PLATS TO THE SOUTHWEST.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-5: I REPLACED THE 1" IRON PIPE WITH A CONCRETE MONUMENT WITH BRASS TAG #31606  
N 10 W. 68.88' to remon tag E. side power pole.  
S 85 W. 45.50' to remon tag N. side 4" tree.  
S 50 W. 75.55' to remon tag N.W. side 18" maple.  
S 20 W. 107.93' to top center fire HYD.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDNCE OF THE ORIGINAL CORNER.

Signed by [Signature]

Date DECEMBER 19, 1994

Surveyor's Michigan License No. 31606