

**SURVEY & REMONUMENTATION**

AUG 24 1995

**COMMISSION**

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Osceola (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____ S <u>21</u> T <u>17N</u> R <u>8W</u>	<u>001</u>
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Osceola County

*Matthew McClung*  
August 3, 1995

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Matthew McClung

July 26, 1995

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9		<i>opl</i>											
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													


**A. Description of original monument and accessories and/or subsequent restoration:**

This corner appears in the CRS records evart township book, on pages 30 and 31. No date or name of the surveyor is given. It also is shown in the front page, page 4, mid page.

I have shown 4 P.A. 132 surveys, by McClung and Wetherell.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

Found South 1/16 Corner west Line of Section 21. Corner is a 1/2" rod 5" below road surface. Placed Osceola County Monument over iron and placed 6" below road surface. I found remains of 10" Elm NE 50.50 feet.



**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

South 1/16th Corner West Line Section 21, Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.

- 12" Scotch Pine N08E 203.04 feet.
- Plat Monument N06E 246.475 feet.
- 14" Scotch Pine N02E 265.30 feet.
- Plat Monument North 406.995 feet.

*Janey Campbell*  
**OSCEOLA COUNTY REGISTER OF DEEDS**  
**95 AUG - 9 PM 12: 14**

July 26, 1995

Signed by *Matthew McClung* Date \_\_\_\_\_  
Surveyor's Michigan License No. 13037