

JEC 21 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda (County) Located In: Corner Code #
1. Public Land Survey T 27N R 2E E-5
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

Liber 5 pg. 103

STATE OF MICHIGAN
OSCODA COUNTY
FILED

9 AUG 2000 3:42:38 PM

PATSY J. PETERS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Marvin E. Myers, in a field survey on June 28, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

Grid table with columns A-M and rows 1-13. A dot is marked at the intersection of row 5 and column E.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration.

Corner common to Sections 8, 9, 16, 17, T27N, R2E
GLO 1839 W. Coon, DS 1887 John Randall, CS 1969 N. C. Caldwell, PS #12018
Mon. - Post Mon. - Set Post Mon. - Found 1/2" bar Placed Standard Co. Corner
Wit 9" Spr. Pine N16°W 19 lks Wit: 16" Y. Pine N66°E 219 lks Wit: 8" J. Pine S15°E 34.45'
9" Spr. Pine N80°E 7 lks No Other 12" J. Pine N70°W 45.00
12" J. Pine N10°W 16.1
1/2" bar & post South 33.00
LCRC L2, P170 (same data)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner common to Sections 8, 9, 16, 17, T27N, R2E
Found Standard Oscoda County Monument 5' North of E-W Road; found 8" J. Pine S15°E 34.45; found 1/2" bar & post South 33.00. Accepted Standard County Corner as the best available evidence of the position of the Original Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner common to Sections 8, 9, 16, 17, T27N, R2E
Mon - Standard Oscoda County Monument.
Wit: Nail in W. side 15" Norway S05°E 23.66
Nail in NW side 5" Poplar S33°W 30.29
Nail in S. side 5" Poplar N40°W 23.20
Nail SE side 4" Maple N45°E 19.11

APPROVED
County Remonumentation
Peer Review Group
NCC
27 JULY 00



Signed by [Signature]
Surveyor's Michigan License No. 31600

Date July 10, 2000