

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

OSCODA Located In: ELMER Corner Code #  
(County)

1. Public Land Survey T 27N R 2E E-8  
T \_\_\_ R \_\_\_  
T \_\_\_ R \_\_\_  
T \_\_\_ R \_\_\_

2. Property Controlling S \_\_\_ T \_\_\_ R \_\_\_  
in Section S \_\_\_ T \_\_\_ R \_\_\_

3. Miscellaneous S \_\_\_ T \_\_\_ R \_\_\_  
Property in Sec. S \_\_\_ T \_\_\_ R \_\_\_

Liber 5 pg 68

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

15 SEP 1999 9:49:24 AM

PATSY J. PETERS  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, FREDERICK J. KING, in a field survey on June 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21

- Nov. 1839 - William R. Coon, Dep Sur - Set orig. Post \*N55°E-10 lks (6.60') 6" Pn \* S34°W- 16 lks (10.56') 6" Pn
- 1887 - John Randall, Co Sur - Re-Set Post Midway and on Line - N56°W-65.3' -12" W. Pine \*S38°E-21.8' - 24" Norway
- 1963 - Field Notes by N.C. Caldwell, PS#12018 - Set 3/4" Pipe & Post by Sngl Prop. - Randall N.B.T's Check this Location \* N56°W - 65.3' -12" W. Pn (stump) Blaze - S38°E -21.8' -24" N. Pn (Stump) Mrks Visible New B.T's Mrkd - N20°E- 25.5' - 12" Oak - N80°W -32.1' - 24" N. Pn Stump- S47°E- (8.6'- 12" Oak
- Oct. 1965 - Field Notes by N.C. Caldwell, P.S.#12018 - Cor Fnd - No Cor Desc - No Wit.
- 1968 - Advised by N.C. Caldwell, PS#12018 on 7-9-99 - He used Corner
- June 1969 - Sec. Div Sur by Harold Dorcey, PS#9429 - Set Cons Pwr Co "T"-Iron by Sngl Prop - No Wit.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21

Found Consumer Power Company "T"-Iron & N.C. Caldwell 1963 Witnesses

APPROVED  
County Remonumentation  
Peer Review Group  
SEPT 99  
NCC

THIS CORNER APPROVED BY OSCODA COUNTY PEER REVIEW ON JULY 9, 1999 AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21

Replaced Cons Pwr Co "T" Iron with 1/2" Iron (Wrapped with Elec Tape) & Oscoda County Re-mon Cap with Carsonite Marker Post on W. side.  
N25°E - (R-N20 E) - 25.92'(R-25.5') - Set S&T on E side 18" Oak  
N50°E - 26.31' - Set S&T on SE side 10" Oak  
S47°E - 18.81' (R-18.6') - Set S&T on SW side 20" Oak  
S15°E - 37.64' - Set S&T on W side 10" Oak  
S75°W - 34.80' - Set S&T on N side 6" Oak  
N80°W - 32' (R-32.1') - Fnd Stump Remains  
Corner Is + 115' E of N-S Pwr Line.

Signed by Frederick J. King  
Surveyor's Michigan License No. 25852

Date August 28, 1999

