

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: <u>Oscoda</u> (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____	_____
2. Property Controlling in Section	T _____ R _____	_____
	S <u>31</u> T <u>28N</u> R <u>2E</u>	<u>9</u>
	S <u>31</u> T <u>28N</u> R <u>2E</u>	<u>13</u>
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on December 15, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31	●	32		33		34		35		36		
13		●											

A. Description of original monument and accessories and/or subsequent restoration:

9 - CE 1/16 Corner, Section 31, T28N,R2E

None

13 - SE 1/16 Corner, Section 31, T28N,R2E

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

9 - CE 1/16 Corner, Section 31, T28N,R2E

Set a 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

13 - SE 1/16 Corner, Section 31, T28N,R2E

Set a 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9 - CE 1/16 Corner, Section 31, T28N,R2E

Stamped 2" dia. alum. cap on 5/8"x34" rebar
 Witnesses:
 S69°E 18.84' to set N&T on S side 12" J.Pine
 S76°W 15.38' to set N&T on S side 10" J.Pine
 N59°W 4.12' to set N&T on S side 5" J.Pine
 N18°W 19.66' to set N&T on NE side 8" Spruce

Set Blue Carsonite Post w/loc. tag 1' North

13 - SE 1/16 Corner, Section 31, T28N,R2E

Stamped 2" dia. alum. cap on 5/8"x34" rebar
 Witnesses:
 N24°E 29.30' to set N&T on W side 8" R.Pine
 S45°E 13.20' to set N&T on NE side 14" R.Pine
 S56°W 29.79' to set N&T on SE side 10" R.Pine
 N72°W 30.47' to set N&T on S side 16" R.Pine
 S47°W 7' to C/L of NW-SE 2-track

Set Blue Carsonite Post w/loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

1-19-10

