

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 14 T 51N R 40W S _____ T _____ R _____ S 14 T 51N R 40W	5 (GCDB 540460) J6 (GCDB 540440)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 5 09/08/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 14) Center-North 1/16 corner, Section 14. Not previously monumented.

(J6) Center of Section 14. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 14) Established the position for the corner midway and on a straight line between Quarter
corner 1314.25' north and the Center of Section 14 1314.25' south.

(J6) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Poplar East 18.0' mrkd "1/16S BT"
7" Ash S09°E 32.8' do
Power pole N24°W 21.5'
C/L of sign post N80°W 38.0' no nail/tag
Set sq'd cedar post adjacent.
E= 7821097.198 N= 228889.604

(J6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N56°E 12.05' mrkd "C1/4 BT"
9" Sugar S35°E 10.6' do
7" Sugar S20°W 15.2' do
9" Basswood N33°W 13.5' do
Set sq'd cedar post adjacent.
E= 7821085.111 N= 228489.242

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID DL6162: N= 233745.718 m. E= 7824690.922 m.

Signed by Stephan J. Szyszkoski Date 10/06/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division