

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle
(County)

Located In:

Corner Code ~~##~~

- | | | | | | | |
|------------------------------------|---|------------|---|------------|------------|-------|
| 1. Public Land Survey | T | <u>35N</u> | R | <u>03E</u> | <u>A-5</u> | |
| | T | <u>35N</u> | R | <u>03E</u> | <u>B-5</u> | |
| | T | <u>35N</u> | R | <u>03E</u> | <u>C-4</u> | |
| | T | <u>35N</u> | R | <u>03E</u> | <u>B-4</u> | |
| 2. Property Controlling in Section | S | _____ | T | _____ | R | _____ |
| | S | _____ | T | _____ | R | _____ |
| 3. Miscellaneous Property in Sec. | S | _____ | T | _____ | R | _____ |
| | S | _____ | T | _____ | R | _____ |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Carl R. Johnson, in a field survey on August 23, 19 90, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-5 Found monument in place as recorded from previous survey.
- B-5 Set monument at fence corner E-W and S. Best available evidence of corner restoration.
- C-4 Found iron bar in place from unknown original best available evidence to restore corner.
- B-4 Corner established at the true computed intersection of $\frac{1}{4}$ lines.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5 SW corner section 7
 Found wheel hub in "T" Rd. Int.
 3'S & 3'W of Road b's
 Power Pole N28W 64.42'
 Maple 14" S55W 68.75
 Apple 18" N70E 75.4

C-4 E $\frac{1}{4}$ corner sec. 7
 Found $\frac{1}{2}$ " Iron Bar
 raised with $\frac{3}{8}$ " I.R.
 Jackpine 6" N59W 38.29
 Jackpine 6" S61W 31.80
 Dbl.spruce 24" S16E 43.55
 fence post N75E 32.45

B-4 Center of section 7
 5/8" Iron Rod with cap
 Balsam 3" N62E 14.4'
 Balsam 3" S05W 25.6'
 Balsam 4" N65W 15.7'

B-5 S $\frac{1}{2}$ corner sec. 7
 fence corner - fences E-W & S

Set DNR Mon.
 Maple 8" S46E 34.05'
 Maple 20" N50E 5.84 Apple N43W 66.05
 Beech 8" S43W 15.20'
 Signed by Carl R. Johnson

Date 9/17/90

Surveyor's Michigan License No. 30083

