

94 DEC 16 AM 9:41

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

REMONUMENTATION SURVEY & REMONUMENTATION  
For corners in Sanilac  
APR 10 1995  
COMMISSION

LIBER NO. 2 PAGE NO. 30  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_

1. Public Land Survey T 10N R 15E B - 11  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Milletics, in a field survey on Aug 18, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B - 11 GLO Notes  
 Set 1/2 Section Post: Sugar 24 N 46 E 41, B Oak 20 S48 1/2 W 29

Act 74 Form NONE  
 Act 132 Form Liber 3 Page 514, Approved Peer Board Meeting  
 Dec. 16, 1994 97

MDOT Right of Way Book Page 55

Road Comm NONE  
 Drain Comm NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 11  
 S 1/4 Corner Section 30 T10N-R15E  
 Found Monu Box - Raised Monu Box with resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 11  
 S 1/4 Corner Section 30 T10N-R15E  
 Found Monu Box  
 S30°W 73.05 to a nail in a Riser Pole  
 S45°E 44.03 to a Road Sign  
 N35°E 95.25 to a nail in a Power Pole  
 N45°W 38.85 to a Road Sign  
 Monu Box exists 1.0 South of Road Centerline



Signed by John A Milletics Date Dec 10, 1994  
 Surveyor's Michigan License No. 25859