

004 PG 037

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

JUN 27 12 47 PM '94

For corners in

ST. JOSEPH

(County)

Located In:

Corner Code #

FABIUS TWP.

1. Public Land Survey	T 6 S R 12 W	L-1
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Cynthia R. Jancost
REGISTER OF DEEDS
ST. JOSEPH MICH

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, DAVID W. MOSTROM, in a field survey on JUNE 13, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L-1) NORTH 1/4 COR. SEC. 1, T6S, R12W

GLO	LCRC (BOOK 2, PG. 281)	LCRC (BOOK 3, PG. 202)
NOT SET	1/2" X 18" CAPPED IRON BAR SET IN PLACE OF BENT IRON FOUND 16" WALNUT = N60°E 46.06' IRON BAR = SOUTH 33.0' T5S, R12W CORNER = WEST 22.11' CORNER IS 2' N. OF Q NULL RD. CORNER IS 2' E. OF FL PROJ. FROM SOUTH	FOUND CAPPED IRON #14100 22.10' E'LY OF S 1/4 COR. SEC. 36, T5S, R12W 16" WALNUT = N65°E 45.62' U.P. = S04°W 32.85' STOP SIGN = N60°W 63.40'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L-1)
FOUND CAPPED IRON BAR #14100/#32339
AS PER ABOVE WITNESSES (ALL WITNESSES IN AND OK)

SURVEY &
REMONUMENTATION

AUG 3 1 1994

COMMISSION

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON June 13, 1994
Walter CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L-1)
SET 5/8" X 24" IRON BAR W/STANDARD CAP IN MON. BOX IN PLACE OF IRON FOUND
SOUTH 1/4 COR. SEC. 36, T5S, R12W = WEST 22.11'
Q ROAD = SOUTH 2.0'
FENCELINE TO SOUTH = WEST 2.0'
CAPPED IRON NO. 27451 = SOUTH 33.0'
PK NAIL & WASHER 1.0' HIGH ON N. SIDE OF 20" WALNUT = N58°E 46.06'
PK NAIL & WASHER 1.0' HIGH ON W. SIDE OF P. POLE = S12°W 33.34'



Signed by *[Signature]*

Date JUNE 16, 1994

Surveyor's Michigan License No. 32339

REMONUMENTATION