

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Schoolcraft COUNTY
40
T 39 N R 17 W

DESCRIPTION OF CORNER 1/4 corner for sections $\frac{31}{6}$ T40N R17W
6 T39N R17W

CORNER MONUMENT Wood post

DATE MONUMENT PLACED AND WITNESSED 10/9/70, F. J. Bray, McDonald, Filay, Collins

WITNESSES TO CORNER..... 5" Cedar (1/4 S) (NBT) N 05° W, 4.8'



7" Cedar (1/4 S) (NBT) N 77° E, 4.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from a down white pine, original B.T., with upper and lower faces, notch and partial scribe marks visible. Cedar stump with face in poor condition in proper bearing and distance for the other B.T. Corner was found by hand compassing and chaining.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 11/5/70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68