

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45-46 N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. Common to Secs. 4 and 33.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6-27-63

WITNESSES TO CORNER..... 10" Jack Pine ($\frac{1}{4}$ S. N.B.T.) N. 13° E., 25 lks.



10" Jack Pine ($\frac{1}{4}$ S. N.B.T.) N. 66° W., 20 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single Proportionate measure along Township line. No evidence of Original Cor.

Placed Location poster on Road 2 Chs. West of Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/11/83
REGISTERED LAND SURVEYOR