


MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



LAND CORNER RECORD

T. 46 .. NR. 15 .. W

.. Schoolcraft .. COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 28 and 29 .....

DESCRIPTION OF CORNER MONUMENT .. 1" Pipe with 4" Brass Cap .....

WITNESSES TO CORNER .. 6" Tamarack .. (1/4<sup>s</sup> NBT) .. N 45° W .. 24 Links ..

5" Spruce .. (1/4<sup>s</sup> NBT) .. N 41° E .. 35 Links ..

-----  
-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between Section Corners. No evidence of original corner.

Corner was placed and witnessed July 25, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/12/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler