

APR 08 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Shlawassee Located in: _____ Corner Code # _____
(County)

1. Public Land Survey T 8N R 1E _____ (L-13)
T _____ R _____
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
In Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

RECORDED

95 NOV 22 PM 1:19

REGISTER OF DEEDS

Spivey
SHLAWASSEE COUNTY, MICH.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Mark L. VanRaemdonck, in a field survey on October 12, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1.) Original: Robert Clark Jr.

Monument: Wood post

Accessories: Lynn 5 N46°E 22

Sugar 11 N74°W 24

2.) H.C. Main, Co. Surveyor, Book B&C, page 158-159

Monument: Not given

Accessories: Beech 13 North 60

W. Ash 2 N2 3/4°E 41 3/4

3.) M.L. VanRaemdonck, L.C.R.C. Liber 2, page 666, 8/25/89.

Monument: Set rerod & cap #24622 using single proportion method between K-13 and M-13
Accessories: N35°E 43.21' N&T W. face 18" Basswood
North 47.50' N&T W. face 12" Hickory
N20°E 113.05' SW corner foundation house #6514
N02°W 74.56' N&T W. face 30" Oak

4.) M.L. VanRaemdonck, Survey recorded Liber 5, page 334, 6/20/89.

Monument: Rerod & cap #24622
Accessories: Same as no. 3

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found rerod & cap as referenced in no. 3 above. Found no conflicting evidence. Found no further evidence while excavating for Harrison Marker. Accepted this position as the careful and faithful re-establishment of the corner location.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced rerod & cap with standard Harrison Marker stamped "Remon 24622" and is witnessed by the following accessories:

N35°W 42.91' Set Nail & tag in S. face 18" Basswood
North 47.61' Found N&T #24622 W. face 12" Hickory
N20°E 113.20' SW corner foundation house #6514
N02°W 74.66' Found N&T #24622 W. face 30" Oak
80.15' Set N&T #24622 in S. face 4" Mountain Ash

APPROVED

County Remonumentation
Peer Review Group

OCT 24, 1995

MLV

Signed by

Mark L. VanRaemdonck

Date

Nov. 16, 1995

Surveyor's Michigan License No. 24622

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 16, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983



LIBER LR PG 123