

RECEIVED

1998 DEC 30 PM 2:11

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Linda Loughmiller
WEXFORD COUNTY, MI
REGISTER OF DEEDS

For corners in

Wexford (County) Located In: Corner Code #
1. Public Land Survey T 24N R 09W M-7
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Table with columns A-M and rows 1-13 containing numbers for registration stamp.

I, George D. Smith, P.S., in a field survey on May 18, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- M-7) 1837 GLO Quarter Section Post by John Brink, Deputy Surveyor. Hemlock 9-S28W-15; Hemlock N10W-14
M-7) 1853 GLO Subdivision of T24N-R8W by Thomas Whepley, Deputy Surveyor. Hemlock 8 S10E-13; Hemlock 6 N55 1/2 E-28.
M-7) 1913 Fargo Engineering Co. found remains of two old stakes and both U.S. Witnesses. White Pine stp. 36" N15W 1.86; Cedar 8" N54E 0.61.
M-7) 1981 Roser PS #12028, LCRC Liber 03, Page 259. Found Fargo 3/4" pipe and one Fargo wit.; W. Pine stp. 36" N15°W 122.8. Corner fits US stream tie South +264 very good and US stream tie E 235' Meas. (US = 250' to nearest 1/4 chain). Replaced Fargo pipe with Wexford County Monument. 8" Maple S05°E 10.8'; 7" Maple S73°W 39.1'; 9" Cedar N82°W 26.10'; Creek (2' wide) S 257' ± C. wly.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Wexford County Monument in Southwest corner of clearing and 3 witnesses from 1981 Roser PS #12028 LCRC. This corner is accepted as a careful and faithful perpetuation of the position of the original corner being the section corner common to Sections 13 and 24, T24N, R9W and Sections 18 and 19, T24N, R8W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Wexford County Monument with aluminum cap in Southwest corner of clearing, stamped SE 13, 1998, PS 39098.
8" Maple East 13.12'
12" Maple S04E 10.78' (10.8' Roser)
8" Maple S75W 39.30' (39.1' Roser)
10" Cedar N80W 26.49' (26.1' Roser)

Peer Group Reviewed and Approved
Date: 4 December 1998
Richard D. Wilcox, Wexford County Surveyor

Signed by George D. Smith
Surveyor's Michigan License No. 39098



Date 12-9-98