

APR 24 1995

COMMISSION

1994 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County  
Remonumentation  
Liber 1 Page 94

For corners in

Alcona  
(County)

Located In:

Corner Code

- 1. Public Land Survey T 25N R 9E  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
- 2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
- 3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

I/J-3  
*Other*  
#11  
APPROVED LAND CORNER  
P.A. 345 of 1990  
ALCONA COUNTY

Date 12-21-94  
County Rep. E. J. L.

RECORDED

DEC 21 2 05 PM '94

*Janis A. ...*  
REGISTER OF DEEDS  
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1					
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					

I, David B. Guthrie in a field survey on November 10, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
1843: G.L.O. Survey by Mullett & Burt - Set Post and Referenced Cedar 16 - N4W - 29 / W.Birch 12 - S1W - 30

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
1994: Found 1/2" Iron Rod, R.L.S. #16050 R.L.M.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
1994: Replaced with 5/8" Iron Rod with 3" Aluminum Cap stamped to identify the Corner.  
Referenced -  
N83°W - 10" Cedar - 22.51 feet  
N74°W - 4" Cedar - 19.12 feet  
N32°W - 6" Cedar in clump - 36.69 feet  
S56°W - 10" Cedar - 83.65 feet



Signed by David B. Guthrie

Date Dec. 21, 1994

Surveyor's Michigan License No. 22435