

1994 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remo... Liber... on page 108
RECORDED
DEC 28 10 05 AM '94

For corners in

Alcona (County) Located In: Corner Code: I/J-5 (M. #016)

1. Public Land Survey T 25N R 9E _____
 T _____ R _____
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

APPROVED LAND CORNER
P.A. 345 of 1990
ALCONA COUNTY
Date: 12-28-94
County Rep. E.J.L.

DEC 28 10 05 AM '94
Janis A. Benthien
REGISTER OF DEEDS
ALCONA COUNTY MICHIGAN

Register of Deeds Stamp & File Number

David B. Guthrie in a field survey on December 27, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: G.L.O. Survey by Mullett & Burt - Set Post and Referenced
W.Pine 14 - S11W - 22 / W.Birch 6 - N21W - 16

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Set 5/8" Iron Rod by extension of the North Line of the Plats of Timberlakes Estates and Timberlakes Estates No. 2.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Replaced with a 5/8" Iron Rod with a 3" Aluminum Cap stamped to identify the Corner.
Referenced -
N02°W - S.E. Cor. Hse.#2975 - 61.90 Feet
N60°W - 12" Oak - 75.30 Feet
N40°W - 6" W.Pine - 74.15 Feet
N86°W - 6" Oak - 61.38 Feet



Signed by D.B. Guthrie Date December 27, 1994

Surveyor's Michigan License No. 22435