

SURVEY & REMONUMENTATION

FEB 17 1994

COMMISSION

001 PAGE 49

Alcona County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners in
Alcona
(County)

Located In:

Corner Code =#

Remon Liber 1 Page 49
Dec 22 1 15 PM '93

- | | | |
|-------------------------|------------|--------------|
| 1. Public Land Survey | T 26N R 8E | K 1.5 (M.P.) |
| | T R | |
| | T R | |
| | T R | (Other #3) |
| 2. Property Controlling | S T R | |
| in Section | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

David A. Guthrie
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David B. Guthrie, in a field survey on Nov. 9, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1843: G.L.O. Survey by Lewis Clason - Set Cedar Post - No References
1973: Plat of Lincoln Shores

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1993: Set Plat corner on the East line of Section 2 on the South side of the Lake by retracement of the Plat of Lincoln Shores.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1993: Set 1/2" Iron Rod with a 3" aluminum cap stamped to identify the corner. Referenced:
S01°W - 18" Maple - 18.90 Feet
S10°E - 8" Birch - 8.44 Feet
S20°E - 14" Maple - 41.16 Feet
S89°W - 20" Beech - 43.25 Feet



Signed by

D.B. Guthrie

Date

December 22, 1993

Surveyor's Michigan License No. 22435