

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

? Alger

(County)

Located in:

Corner Code #

- | | | |
|------------------------------------|---|-------------|
| 1. Public Land Survey | T <u>44W</u> R <u>21W</u> | <u>G1</u> |
| | T <u> </u> R <u> </u> | <u>H1</u> |
| | T <u> </u> R <u> </u> | <u>I1</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling in Section | S <u>3</u> T <u> </u> R <u> </u> | <u>2</u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Keith Sackett, in a field survey on May 8, 19 91, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- | | | | |
|--|--|---|---|
| <u>G1</u> | <u>H1</u> | <u>I1</u> | <u>2</u> |
| Original monument and accessories not found. Found 3/4" iron pin in monument box on state highway. | Quarter corner common to sections 3 and 34. Found County Surveyor Depev corner from early 1900s. | Northeast corner of Section 3, found County Surveyor Depev's corner from early 1900s. | East one-sixteenth corner common to Sections 3 and 34. Not set on original survey nor subsequently, apparently. |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- | | | | |
|----------------------------|-----------------------------|---------------------------|---------------------------------|
| <u>G1</u> | <u>H1</u> | <u>I1</u> | <u>2</u> |
| Restored at 3/4" iron pin. | Restored at Depev monument. | Restored at Depev corner. | Established midway and on line. |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | | |
|--------------------------------|----------------------------|--------------------------------|---------------------------|
| <u>G1</u> | <u>H1</u> | <u>I1</u> | <u>2</u> |
| 3/4" iron pin in monument box. | Depev corner. | Depev monument. | DNR |
| 6" spruce N77E 65.6' NBT | Newlock N48E 11.3' NBT | 36" sugar maple N38E 16.3' NBT | 6" spruce N54E 21.7' BT |
| 4" spruce S57E 46.4' NBT | Sugar maple S72E 13.2' NBT | 7" sugar maple S33E 19.5' NBT | 4" cedar N42E 54.1' BT |
| 5" spruce S71W 72.7' NBT | Red maple S70W 41.2' NBT | 9" sugar maple S20W 3.6' NBT | 6" spruce S39W 17.0' BT |
| 16" cedar N54W 90.2' NBT | Red maple N61W 25.55' NBT | 8" sugar maple N79W 44.4' NBT | 18" v. pine N54W 17.8' BT |

Signed by

Keith Sackett

Date

June 10, 1991

Surveyor's Michigan License No.

19006

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 29, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983

