

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 NR 16 & 17 W

Alger & Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 12, 6, 7

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER 15" W. Pine N 19° W 95 links  
" S 1 NBT"  
8" Cedar S 70° W 15 links  
" S 12 NBT"  
8" Cedar N 71° E 27 links  
" S 6 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Corner from one Cedar B.T. bearing S 70° E, 19 links.  
Tree down but in good condition. Found old cedar post in place.

Corner lies in swamp.

Corner found by Forestry Division Survey Crew while making a partial  
re-survey of this township.

Corner placed and witnessed 1-28-57.

SURVEYORS SEAL

SIGNED *Billy D. Buckles* DATE 2-7-57  
REGISTERED LAND SURVEYOR