

SURVEY & REMONUMENTATION

FEB 19 1998

SECTION

05-62

Approved by Alger County
Land Survey Commission
Peer Group Under Act 545 of
P.A. of 1990 On 12-10-97

Donald W. Carlson
Chairman

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located In:

Corner Code #

County

FILED

TIME 8:30 A.M.

DEC 17 1997

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

- | | | | | | |
|------------------------------------|---|----|---|----|----|
| 1. Public Land Survey | T | 46 | R | 17 | C7 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert L. Jamros, in a field survey on October 31, 1996, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C7: PLS - William Ives, DS, 1850, Post set corner of Sections, 17-18-19 & 20 * Hemlock 15, S.76 W., 22 links * Yellow Birch 16, N.40 E., 22 links ***** Munising Railway Company, East Branch Extension * R.C. Young, Chief Engineer, 1924 * Corner position is shown 1360 feet South of section line crossing at Station 489+50. * Ties ***** W.W. Gleason, CS, 1913 * Standard Iron Corner * SE corner S.18, T.46N., R.17W. * No references given ***** M.S.H.D., Project No. 02022, 1958 * Corner shown on construction plats * No references or monument material shown ***** Billy D. Buckler, RLS, 7-13-81 * Reestablished corner on centerline of North-South road and by single proportionate measure between section corner, 1 mile North and quarter corner, 1/2 mile South * Buried a 36 inch T-Iron in center of Blacktop Road at corner position * Witnesses - White Spruce 16, N.49 E., 50.7 feet * White Birch 7, N.68 W., 41.5 feet * Recorded in Liber 1, Page 396, Alger County Corner Records ***** No other subsequent restoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C7: Found T-Iron (bent) on centerline of asphalt pavement. Recovered the exist. BT's of the 1931 report and 1 other exist. BT, author unknown. Established an additional BT and set new monument. Measurements to corners North, South, East and West, measure well within section * Distance from corner position to centerline of old railroad grade measures 1363 feet * Measurement to a GLO stream call to West of corner measures well, GLO=246 feet and 1997 measure=250 feet. * Corner position has been accepted and used in area surveys. * Monument at exist. corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C7: Replaced exist. T-Iron with 5/8 inch X 16 inch Rebar and a 3 1/4 inch Berntsen cap no. R805325, stamped to identify corner position * Renewed exist. reference trees w/BT signs, paint. * Set PK nails w/Alum. I.D. washers for measure in the following - Exist. BT, Spruce 10, N.52 E., 51.58 feet, blazed and scribed * Exist. BT, White Birch 7, N.64 W., 41.62 feet, blazed and scribed * Exist. BT, Spruce 3, S.72 W., 44.15 feet, face blazed * PK nail w/Alum. I.D. washer on East side of telephone pole stub at and with underground test station box, S.06 E., 139.75 feet * All bearings are magnetic.

Signed by

Robert L. Jamros

Date

12/10/1997

Surveyor's Michigan License No.

25849

