

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 5 T 48N R 15W	5
	S T R	(GCDB 240660)
	S 5 T 48N R 15W	8
	S T R	(GCDB 220640)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 5 06/19/14  
8 06/18/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 5) Center-North 1/16 corner, Section 5. Not previously monumented. Dimensions derived from  
the original 1852 US GLO plat are 20.00 chains south to Center of Section and 20.27 chains north to  
Quarter corner.

(8-Sec. 5) Center-West 1/16 corner, Section 5. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 5) Established the position for the corner on a straight line between Quarter corner  
1341.78' north and the intersection of 1/4 lines of Section 5 1323.91' south, being proportionate to  
the US GLO plat dimensions. The position for the corner falls on the north edge of a MDNR walking  
path.

(8-Sec. 5) Established the position for the corner midway and on a straight line between Quarter  
corner 1330.37' west and the intersection of 1/4 lines of Section 5 1330.37' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" J.Pine S73°W 20.55' mrkd "N1/16 BT"  
6" J.Pine N73°W 47.6' do  
5" J.Pine N77°E 34.7' do  
7" Cherry S16°E 71.4' do  
E= 8060585.113 N= 200958.714

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" Maple S64°W 15.8' mrkd "W1/16 BT"  
12" Hemlock N13°W 5.75' do  
10" Hemlock N69°W 16.85' do  
8" Hemlock S14°E 17.75' do  
E= 8060183.341 N= 200548.752

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RK0012: N= 200478.710 m. E= 8059786.467 m.

Signed by Stephan J. Szyszkoski Date 07/30/2014  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

