

Signed by_

Surveyor's Michigan License No.

idea 2 Danas	Approved by Alger County
JAN 182001	Lond Solvey Rendmunichation Peer Group Under Act 345 of P.A. of 1990 On 12-13 19 2000
SECTION LAND CORNER RECORDATION CERTIFIC	1 1
Filing Requirement of Act 74, Mich. P.A.	
Alger Located In: Corner Code #	05-219
	FILED
Public Land Survey T 48N R 15W M08	TIME 8:50 AM
T <u>48N R 14W A08</u> T R	DEC 2 0 2000
T R	DONALD W. KINNUNEN
in Section S T R	REGISTER OF DEEDS ALGER COUNTY, MI
3. Miscellaneous S T R Property in Section S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	A 3 C D E F G H J K L M
	3
Robert L. Jamros in a field survey on October 20 2000	4 7 8 9 10 11 12 1
to hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention lines 1 and 2 above were in conformance with regulations and rules therefore as required in the cu	oned 6 18 17 16 15 14 13
manual of survey instructions of the United States Department of the Interior, Bureau of Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4	Land /
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or	by a g
Decree of a Court of Law; established, re-established, monumented, recovered, f as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	11
A. Description of original monument and accessories and/or subsequent restoration	13
MO8: PLS William A. Burt, DS, 1841. Set quarter section pospruce 10", N.30°E., 58 links. ***** No other subsequent re	
`	
B. Description of corner evidence found and/or method applied in restoring or reest	tablishing corner:
MO8: Established corner position at midpoint and on li North and South. Found very faint paint lines of timber position. No original G.L.O. evidence was found. Corner as a careful and faithful reestablishment of the position	cruisers North and West from this position as established is accepted
C. Description of monument for corner and accessories established to perpetuate	ocating the position of the corner:
MO8: Set 2½" x 30" Berntsen aluminum monuments no. A1NB3	30 with 34" aluminum cap stamped to

identify corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Hemlock 8",

N.02°W., 27.58 feet (4S BT); Hemlock 10", N.67°E., 26.41 feet (4S BT); Hemlock 11", S.21°E., 19.81 feet (4S BT); Hemlock 15", S.65°W., 33.14 feet (4S BT). Survey marker sign on 6 foot steel post, S.65°E., 0.80 feet. All bearings are magnetic.

25849

Date_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

E OF MICH

ROBERT L. **JAMAROS** PROFESSIONAL SURVEYOR No.

25849 PORCESIONA