

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 35 T 48N R 17W	J12
	S T R	(GCDB 540140)
	S 35 T 48N R 17W	5
3. Miscellaneous Property in Sec.	S T R	(GCDB 5401600)
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 10/09/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J12) Center of Section 35. Found no record of prior monumentation.

(5-Sec. 35) Center-North 1/16 corner, Section 35. Found no record of prior monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J12) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position thus established I found a 2" I.pipe with welded cap, approx. 1.5' tall, set by persons unknown, N72°W 10.0 ft. distant, which I did not accept as marking the position for the corner.

(5-Sec. 35) Established the position for the corner midway and on a straight line between Quarter corner 1318.01' north and Center of Section 35 1318.01' south. From the position thus established I found a 2" I.pipe with welded cap, approx. 1.5' tall, set by persons unknown, N75°W 4.96' distant, which I did not accept as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
12" Sugar N44°W 11.62' mrkd "CS BT"  
7" Sugar S80°W 26.57' do  
19" Sugar N51°E 7.55' do  
16" Sugar S20°W 4.64' do  
E= 8046316.306 N= 192457.385

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
9" Cedar N68°E 6.01' mrkd "N1/16 BT"  
8" Cedar S20°E 9.46' do  
13" Cedar S68°W 6.71' do  
7" W.Birch North 14.68' do  
E= 8046311.522 N= 192859.036

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID DJ8902 : N= 177197.949 m. E= 8027768.701 m.

Signed by Stephan J. Szyszkoski Date 01/19/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number												
A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

