

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 9 T 49N R 13W	2
	S 4 T 49N R 13W	13
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3							3						
4	7		8			9		10		11		12	
5													
6	10		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 2 08/24/2010  
13 09/09/2010 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(2-Sec. 9) East 1/16 corner between Sections 4 and 9. Not established in the original survey.

(13-Sec. 4) Southeast 1/16 corner, Section 4. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec. 9) Established the corner midway and on the Section line between Quarter corner 1302.70' west  
and Section corner 1302.70' east.

(13-Sec. 4) Established the corner at the intersection of straight lines connecting opposite 1/16  
corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Face of metal sign post S30W 6.75'  
Set measuring nail with MDNR tag in the side of:  
22" W.Pine S85E 111.5' mrkd "E1/16 BT"  
8" Maple in clump N30E 68.9' do  
6" Maple N11W 18.95' do  
Bearings are magnetic.

(13) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Tamarack N11E 11.05' mrkd "SE1/16 BT"  
9" Cedar S68E 22.7' do  
5" Cedar S66W 3.4' do  
8" Cedar S22E 14.35' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/01/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

