

JAN 18 2001

Approved by Alger County Land Survey Monumentation Peer Group Under Act 345 of P.A. of 1980 On 12-13-2000

Herold Carlson
Chairman

For corners in SECTION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 13W	G10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

05-193
 FILED
 TIME 8:50 AM.
 DEC 20 2000
 DONALD W. KINNUNEN
 REGISTER OF DEEDS
 ALGER COUNTY, MI
 Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on September 22, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G10: PLS Francis Colman, DS, 1851. Set quarter section post. Fir 8", N.55°W., 9 links. Spruce 10", S.49°E., 38 Links. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G10: Established corner position by single proportionate measurement and on line between section corner 1/4 mile North and 1/4 section corner 1 mile South. No corner monument found. Corner position lies 8 feet West of West edge of dirt road. No original G.L.O. evidence found at corner position. G.L.O. terrain calls to North and South check reasonable well. Corner position as established is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G10: Set 2 1/2" x 30" Berntsen aluminum monument no. A1NB30 with 3 1/4" aluminum cap stamped to identify corner position. Established the following references with BT signs, paint, blazed and scribed. Set PK nails for measure with aluminum I.D. washers in the following: W. Pine 18", S.58°W., 35.10 feet (1/4S BT); Spruce 7", N.23°W., 4.22 feet (1/4S BT); W. Birch 9", N.63°E., 49.86 feet (1/4S BT); Spruce 9", S.54°E., 39.07 feet (1/4S BT). Survey marker sign on 6 foot steel post, N.77°W., 1.1 feet. All bearings are magnetic.

Signed by *Robert L. Jamros*
 Surveyor's Michigan License No. 25849

Date Dec. 17, 2000

