

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000Donald W. Kinnunen
Chairman

05-197

SECTION

LAND CORNER RECORDATION CERTIFICATE

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

Alger

(County)

Located In:

Corner Code #

- | | | | | | |
|--------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 49N | R | 13W | I11 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | | |
| | S | | T | | |
| 3. Miscellaneous Property in Section | S | | T | | |
| | S | | T | | |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

FILED

TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on July 25, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I11: PLS Francis Colman, DS, 1851. Set post corner of sections 26, 27, 34 and 35. Maple 12", North 26°E., 8 links. Hemlock 14", S.14°W., 54 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap on line and at single proportionate measurement between corners on each end of 3 mile random as run in original survey. 30" W. Pine stump, (S35 NBT) S.36°E., 173½ links. 40" W. Pine (NBT) N.84°W., 103 links. 26" W. Pine stump (S34 NBT) S.25°W., 150 links. Liber 2, Page 93, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I11: Found 1" iron pipe with 4" brass cap and 3 NBT's of the 1960 report in good condition. Corner monument as found lies 2.4 feet South and 1.2 feet East of proportional position on line between corners on each end of 3 mile random as run in original survey. No original corner evidence found. Existing corner monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I11: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs and paint. Established additional reference tree with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine stump 30", S.34°E., 116.65 feet; Ex. NBT, W. Pine stump 40", N.81°W., 68.0 feet; Ex. NBT, W. Pine stump 26", S.28°W., 99.06 feet; J. Pine 5", N.24°E., 41.49 feet (BT). Survey marker sign on 6 foot steel post, S.70°W., 1.0 feet. All bearings are magnetic.

Signed by

Robert L. JamrosDate Dec. 17, 2000

Surveyor's Michigan License No.

25849