

JAN 18 2001

Approved by Alger County Land Survey Remuneration Peer Group Under Act 345 of P.A. of 1990 On 12-13-2000

Donald W. Kinnunen
Chairman

SECTION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger (County)	Located in:	Corner Code #
1. Public Land Survey	T 49N R 13W	K11
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

FILED 05-202
 TIME 8:50 AM
 DEC 20 2000
 DONALD W. KINNUNEN
 REGISTER OF DEEDS
 ALGER COUNTY, MI
 Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on September 18, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K11: PLS Francis Colman, DS, 1851. Set post corner of Sections 25, 26, 35 and 36. W. Pine 14", N.41°E., 40 links. Spruce 14", S.20°W., 11 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap from 1 original W. Pine BT bearing N.E. of corner. W. Pine 8", (S26 NBT) N.52W, 111½ links. W. Pine 8" (NBT) N.83°E., 76 links. W. Pine snag (NBT) S.05°E., 39.5 links. Liber 2, Page 86, Alger County corner records. No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K11: Found 1" iron pipe with 4" brass cap and 1 of the NBT's in good condition. W. Pine snag in S.E. bearing now a decayed stump and W. Pine 8" in N.W. bearing has become a 12" dead stub. Found stump remains of original W. Pine BT bearing N.E. from corner monument position. Existing corner monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K11: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT with a BT sign and paint. Established additional reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine 30", N.85°E., 50.16 feet (blaze scars); W. Pine 6", S.39°E., 32.93 feet (S36 BT); W. Pine 7", S.11°W., 20.37 feet (S35 BT); W. Pine 10", N.28°W., 14.76 feet (S26 BT). Survey marker sign on 6 foot steel post, S.86°W., 1.5 feet. All bearings are magnetic.

Signed by *Robert L. Jamros* Date Dec. 17, 2000
 Surveyor's Michigan License No. 25849

