

JAN 18 2001

Approved by Alger County  
Land Survey Monumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12-13-2000

Gerald A. Carlson  
Chairman

05-197

For corners in SECTION

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

Alger  
(County)

Located In:

Corner Code #

**FILED**

TIME 8:50 AM.

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

**Register of Deeds Stamp & File Number**

		50N	13W	M.C. K11-12
1. Public Land Survey	T	_____	R	_____
	T	_____	R	_____
	T	_____	R	_____
	T	_____	R	_____
2. Property Controlling in Section	S	_____	R	_____
	S	_____	R	_____
3. Miscellaneous Property in Section	S	_____	R	_____
	S	_____	R	_____

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Robert L. Jamros, in a field survey on May 30, 2000  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, recovered, found  
as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

MC K11-12: PLS Francis Colman, DS, 1851. Intersect Lake Superior C East and West and set meander post on top of bank, 50 feet. W. Pine 6", S.74°W., 35 links. Fir 10", S.71°E., 66 links. \*\*\*\*\* No other subsequent restoration of record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

MC K11-12: Established witness corner to meander corner on section line extended from section corner and quarter section corner to the South at 1069.3 feet North of quarter corner. Record=1589.3 feet. Erosion has moved bluff inland 325 feet. Set monument for witness corner position and established reference trees.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**MC K11-12:** Set witness corner to Meander Corner, Berntsen aluminum monument no. A1NB30 with 34" aluminum cap stamped to identify witness corner position, 520 feet South of the meander corner. Established the following reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: J. Pine 7", N.47°E., 21.91 feet (WC BT); J. Pine 7", S.56°E., 14.03 feet (WC BT); R. Pine 7", S.60°W., 22.71 feet (WC BT); J. Pine 7", N.66°W., 32.16 feet (WC BT). Survey marker sign on 6 foot steel post, N.31°E., 1.5 feet. Witness corner position is 195 feet South of top of bluff. All bearings are magnetic.

Signed by Robert E. James  
Surveyor's Michigan License No. 20849

Date Dec. 17, 2000

