## ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, MICH. P. A. 1970

FILE	
U	ט ע נשניא

ÇŌ


FOR CORNERS IN: LOCATED IN: CORNER CODE # **ALLEGAN COUNTY** T. 1N 1. Public Land Survey R. 12W H-I NORTH 1/4 POST R..... SECTION 3. T.1N., R.12W. OTSEGO TWP. T..... R..... · T..... R..... 2. Property Controlling S......R..... in section S.....R..... 3. Miscellaneous S......R...... Property in Sec.

REGISTER OF DEEDS STAMP & FILE NUMBER

4. Lot No.....Recorded Plat..... 5. Private Claims....

i, Raymond Moored in a field survey on Dec. 20, 1999 do hereby state that under requirments of P.A. 74, Michigan P.A. of 1970, corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in the lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below.

Note: Not more than 2 corners, all the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
  - THIS POSITION WAS NOT ESTABLISHED BY G.L.O.
  - 2. JULY 17, 1974, J.M. BUDBIK P.S., BOUNDARY SÜRVEY, N.E. 1/4 SEC-3 T.1N., R.12W. 1R 3'+/- S C/LNAIL W FACE 14" OAK N30°E 30.82'
    NAIL W FACE 12" OAK N10°W 26.03'
    NAIL W FACE 16" OAK S40°E 36.34'
    SURVEY SHOWS FE TO S IS W 2'+/-

(H-1) TO (I-1) MEASURES 2640.44"

J.M. BUDZIK, P.S., FEB. 1975, L.C.R.C. RECORDED L.002, P.367 PART "B": FND. NW & NE CORS, SECTION 3, SPLIT MILE PART "C": SET IRON ROD

SET IRON ROD

NAIL W. FACE 14" OAK N30E 30.82'

NAIL W. FACE 12" OAK N10W 26.03'

NAIL W. FACE 16" OAK \$40E 36.34'

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990 ALLEGAN COUNTY

DATE APPROVED MARCH 9 19 COUNTY REP. Wild. Um Out COUNTY REP.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SET STANDARD ALLEGAN COUNTY REMON IRON AND CAP MID-WAY BETWEEN G-1 AND I-1, T.1N., R.12W., OTSEGO TWP AND ON LINE BETWEEN H-13 AND G-13, T2N, R12W.

THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER.

APPROVED BY THE ALLEGAN COUNTY REMON PEER GROUP ON MARCH 9, 1999.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD 3/4" X 24" ALLEGAN COUNTY REMONUMENTATION IRON WITH CAP

- -NAIL IN EAST SIDE 24" OAK S9W 39.50' -NAIL IN WEST SIDE WOOD FENCE POST N55E 43.63' -NAIL IN EAST SIDE WOOD FENCE POST N66E 59.43'

- -H-13, T2N, R12W EAST 46.5' -NAIL IN SW SIDE 8" POPLAR N42W 79.43'

Surveyors License No. 26463

