

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF--   | LOCATED IN-- | CORNER CODE NUMBER |
|--|--------------|--------------------|
| 1. PUBLIC LAND SURVEY <u>26</u> T. <u>2</u> N. R. <u>14</u> E.             |              | J-11, K-10, K-11   |
| 2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W.   |              |                    |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W. |              |                    |
| 4. LOT NO. _____, RECORDED PLAT _____                                      |              |                    |
| 5. PRIVATE CLAIMS _____  |              |                    |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

|                           |                    |   |
|---------------------------|--------------------|---|
| J-11 1" Iron              | K-10 1" Iron       | K-11 1" Axle in 30" of<br>of water 1 foot ex-<br>posed. |
| SE 14" Oak 28.1'          | NNE 14" Oak 45.8'  |   |
| SW 12" Oak 16.5'          | NORTH 6" Trail 15' |   |
| NW 10" Oak 24.0'          | NE 10" Oak 76.5'   | South 12" uprooted<br>stump 8'                          |
| SOUTH Gas line P.I. 176'+ | SE 36" Oak 72.2'   |   |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

|                                 |                                |                                  |
|---------------------------------|--------------------------------|----------------------------------|
| J-11 Found 3/4" Iron            | K-10 Found 1" Iron south       | K-11 Found axle in pot hole      |
| S 44° W 12" R. Oak 17.26' Spike | side of road; west side        | S 63° E 10" Willow 31.92' Spike  |
| N 32° W 12" R. Oak 24.58' Spike | of drive.                      | S 70° W 5" Willow in             |
| S 61° E 10" W. Oak 17.48' Spike | S 42° E 33" Oak 72.88' Spike   | clump of                         |
|                                 | N 21° E 22" Oak 49.20' Spike   | three 30.76' Spike               |
|                                 | S 71° W 6" Cherry 23.56' Spike | S 03° W 28" R. Oak 180.93' Spike |
|                                 | in clump                       |                                  |
|                                 | of three                       |                                  |

R6207 R6208 R6209

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Donald L. Bissell DATE 1-30-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18655