

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena

(County)

Located In

Corner Code #

1. Public Land Survey	T	29N	R	8E	H-3
	T				
2. Property Controlling in Section	S	4	T	29N	R 8E
	S		T		5
3. Miscellaneous Property in Section	S		T		R
	S		T		R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 12, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

H-3 – South ¼ Corner Section 3, T29N,R08E

5-CN 1/16 Corner, Section 4, T28N,R08E

1839 – GLO – Lewis Claison – Set qr. sec. post.  
W. Pine 24" N24°E 26 Links  
Fir 18" S40½°W 12 Links

This corner position was not set during the Original Government Survey

1973 – L.C.R.C. L. 1,P. 21 D. Marlatt P.S. #18660  
Found 4"x4" cedar post set concrete Mon.

N30°E 18.45' 12" Ash  
N60°W 15.5' 18" Poplar

2006 Certificate of survey Liber -3, Page-692  
Duane R. MacNeill P.S. #19237 found concrete monument for corner no witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

H-3 – South ¼ Corner Section 3, T29N,R08E

5-CN 1/16 Corner, Section 4, T28N,R08E

Found a concrete monument leaning Northwesterly fitting D. Marlatt and Duane MacNeill's distances for the South line for section 3. Straightened and lowered monument.

Set 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-3 – South ¼ Corner Section 3, T29N,R08E

5-CN 1/16 Corner, Section 4, T28N,R08E

Reset conc. Monument flush with ground and added P.S. Cap# 33981

2" dia. stamped aluminum cap on 5/8"x34" rebar

Witnesses:

Witnesses:

N40°E 2.44' to set N&T on W side 7" Ash  
S15°E 69.05' to set N&T on E side 14" R. Maple  
N18°W 70.33' to set N&T on W side 7" Balsam Fir  
N25°W 13.75' to set N&T on SW side 7" Ash  
Center East-West power line ROW South 36'

N80°E 40.30' to set N&T on S side 8" W. Pine  
S23°E 26.39' to set N&T on SW side 3" Balsam Fir  
N79°W 48.98' to set N&T on S side 6" Balsam Fir  
N27°W 40.51' to set N&T on SW side 13" R. Maple  
North 9' to barbed wire fence going West

Set Blue Carsonite Post w/loc. tag 1' North

Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

2/9/11

Surveyor's Michigan License No.:

33981

