LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				
Alpena (County)	Located In:	Corner Code #		
1. Public Land Survey	TR			
 Property Controlling in Section Miscellaneous Property in Sec. 	TR S_2_T_30N_R_7E S_2_T_30N_R_7E STR STR	5 15	Register of Dec	eds Stamp & File Num
4. Lot No, Recorded Plat				
I, <u>Carl T. Kiiskila</u> , in a fi state that under requirements of mentioned in lines 1 and 2 above therefore as required in the curre States Department of the Interior	P.A. 74, Michigan P.A. of 1976 were in conformance with rent manual of survey instructions, Bureau of Land Management	9 99 do hereby 70, the corner points gulations and rules ns of the United t or by a decree of a	A B C D E F G 1	H I J K L M -3 -2 -1 - -10 -11 -12 - -15 -14 -13 - -22 -23 -24 -
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			10 30 29 28 11 12 31 32 33	-27 26 25 36
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				
A. Description of original monument and accessories and/or subsequent restoration:				
5 - This corner position was not established during the original government survey. 15 - This corner position was not established during the original government survey.				
B. Description of corner evidence	dence found and/or metho	d applied in restoring or reest	tablishing corner:	
5 - Established the Northeast corner of the Southeast quarter of the Northwest quarter of Section 2 per standard B.L.M. instructions for subdivision of a section. 15 - Adjusted Marcus Schaaf's, RLS #3104, 1-1/4" iron pipe to the correct position for the Southwest corner of the Southwest quarter of the Southwest quarter of Section 2 per standard B.L.M. instructions for subdivision of a section.				
C. Description of monument	t for corner and accessorie	es established to perpetuate lo	ocating the position of the corner:	
Wit: Set nail in 1 Set nail in 7 Set nail in 1 Set nail in 8 Concrete pl	rod with PS cap and carson 6" Red Pine S 8° W " Jack Pine N 73° W 2" Jack Pine N 7° W " Jack Pine S 86° E at monument N 66° W	ite marker post. 15 - Set a 4.36' Wit: 16.36' 13.08' 43.97' 30.58'	a 1-1/4" iron pipe and carsonite ma Set nail in 12" & 6" twin Maple Set nail in 16" Maple clump Set nail in 7" Ash Set nail in 9" Maple Carsonite post	rker post. S 61° W 35.95' N 21° W 46.84' N 31° E 37.09' S 68° E 10.36' North 1'
gravel ro Carsonite p	oad East	17' 1' CARL KIISKILA LAND SURVEYO No. 33981	**	
Signed by Oarl	T Kuski	La NSED LAND	SURVE SURVE 8 - 12	2-99
Surveyor's Michigan License				