

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena

(County)

Located In

Corner Code #

1. Public Land Survey	T	31N	R	6E	L-4
	T	31N	R	6E	L-3
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on, May 5 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-4 This corner position was not established during the original government survey.

L-3 G.L.O. Butler Ives 1855 Set section post  
Wit: Spruce 10 N62°E 15 links  
Maple 7 S58°W 14 links

R.S. Scott's October 1980 survey by David B. Guthrie P.S.  
#22435 shows an existing 1" pipe for corner.  
Wit: 5" Spruce N20°W 27.60'  
4" Balsam S45°W 10.30'  
4" Balsam S20°E 5.33'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-4 Established the center of section 12 at the intersection of the North-South and East-West quarter lines.

L-3 Found ¾" X 24" pipe replaced with 1" X 32" pipe with standard DNR aluminum cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-4 Set 5/8" X 32" rerod with P.S. cap #33981

Wit: 3" Maple N66°W 37.49'  
12" Maple N11°E 65.93'  
3" Balsam East 72.10'  
P.K. in large Rock N37°W 66.55'

L-3 Set 1" X 32" pipe with standard DNR aluminum cap.

Wit: 4" Balsam S50°E 15.58'  
8" Balsam S40°W 10.30'  
6" Balsam N12°E 28.11'  
7" Spruce N51°W 35.00'  
Carsonite post North 1'±

Signed by:

Carl T. Kiiskila

Date:

3-22-04

Surveyor's Michigan License No.:

33981

