

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners in:
Alpena _____ Located In _____ Corner Code # _____
(County)

1. Public Land Survey T 31N R 6E L-7
T _____ R _____
2. Property Controlling in Section S 13 T 31N R 6E 15
S _____ T _____ R _____
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on, May 7, 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	5		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	8		17		16		15		14		13		
7													
8	9		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-7 G.L.O. Butler Ives 1855 set quarter section post
Wit: Cedar 8 N03°W 6 links
W. Pine S39°W 6 links

15- This corner position was not established during the original government survey.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-7 Found a Marcus Schaaf monument either pulled out or never set. Set a standard DNR monument at an old fence corner with wire going South and East

15- Established the Southwest corner of the Southeast quarter of the Southwest quarter of section 13 as per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-7 Set 1" X 48" pipe with DNR aluminum cap.
Wit: 5" Cedar S85°W 26.44'
12" Cedar N18°E 27.11'
6" Balsam S75°E 9.49'
5" Balsam S06°W 15.74'
Old fence going South and West
Carsonite Post North 1'±

15- Set 5/8" X 32" rerod with P.S. cap #33981
Wit: 8" Triple Maple N50°E 11.28'
6" Cedar S64°E 23.22'
5" Cedar S35°W 25.42'
5" Hemlock N23°W 13.32'
Well Point North 5.75'
Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

3-22-04

Surveyor's Michigan License No.:

33981

