LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:						=							
Antrim		Lo	ocated I	n	Corner Code #	=							
(County)	ш	8 8											
1. Public Land Survey	- 89	aT =		R									
Property Controlling in Section	S 25	√ := T :	31N	 R 6W	1 88					55			
	S 25	т -		R 6W	2								
3. Miscellaneous				111									
Property in Section	S	T		R		12							
	S	_ ^T _		R			Reg	ister (of Dec	ds Stam	p & File) Nun	ber
4. Lot No:	Recorde	ed Plat:			3 3								
5. Private Claims:						1 1	ВС	_ <u> </u>	F	G H	1 1	K	. M
						2	6	- 5	-4-	3 -	2 -	+-1	¦
I, <u>Carl T. Kiiskila,</u> in a field	survey on	Decemb	her 6 20	06 do be	arehy state that under	3 -	╁┼	+	-		-		-
requirements of PA 74, Mi	chigan PA	of 1970.	, the cor	ner points	mentioned in lines 1	4	7	- 8	- 9 -	10	11-		2
and 2 above were in confo	rmance wit	h regula	ations an	d rules th	erefore as required in	5 -	-	_					\vdash
the current manual of sur Interior, Bureau of Land Ma	rvey instruc anagement	or by a	r the Un decree n	ited State f a Court	es Department of the	6	18	_17	16-	15—	14-	₁	3
corner points mentioned in	lines 3, 4 a	and 5 ab	ove were	in confo	rmance with the rules	7	\bot						
of the Michigan Board o	f Land Su	rveyors	or by a	Decree	of a Court of Law;	8	19	-20	21	22		Ш,	
established, re-established	, monumen	tea, reco	overea, n	ound as e	xpressed below:	9							
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.						10	30-	-29	-28-	-27-	26-		5
1 = X,						11	-			-	+	+	-
						12	31	-32	-33-	34-	35-	3	6
	•					13							
A. Description of origina	l monume	nt and a	accesso	ries and	or subsequent restor	ration:							
1- John Ferguson R.L	5. #2459	95 set	a P.K.	nail for	corner 2- This	corner pos	ition	was	not e	stablis	hed d	uring	g th

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- 1- Found PK nail as set by J. Ferguson.

while doing a survey in section 24.

- 2-Established the Northwest corner of the Northeast quarter of the Northeast quarter of section 25 as per B.L.M. instructions for the subdivision of a section.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

			to perpetuate recating the position of the corner.						
1-Found P.K. nail			2- Set 5/8" X 32" iron	rod with P.S. o	ap #33981				
Wit: 9" Spruce	N46°W	78.31'	Wit: 8" Maple	N18°E	23.52				
½" CIR 24595/25854	N07°E	33.02'	5" Balsam	S65°W	14.44'				
11" R. Pine	S30°E	48.45'	2" Pipe	N48°W	5.31'				
6 X 6 Fence Post	S05°W	33.02'	3" Balsam	S87°E	10.31				
Blue Carsonite Post	South	33'±	8" Balsam	S01°E	16.91'				
			Blue Carsonite	1'+					

Surveyor's Michigan License No.:

33981

original government survey.

KIISKILA LAND SURVEYOR

No. 33981