

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 10 T 48N R 32W S _____ T _____ R _____ S 10 T 48N R 32W	H4 (GCDB 440540) 9
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 460540) _____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on 05/22/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H4) Center of Section 10. Not previously monumented.

(9-Sec. 10) Center-East 1/16 corner, Section 10. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H4) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/4 corners.

(9-Sec. 10) Established the position for the corner midway and on a straight line between Quarter  
corner 1320.31' east and Center of Section 10 1320.31' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Spruce N13°W 83.1' mrkd "C1/4 BT"  
4" Spruce S36°E 26.15' do  
9" Spruce S22°W 23.35' do  
5" Balsam S58°W 44.25' do  
Set sq'd cedar post adjacent.  
E= 7900855.002 N= 199532.858

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" Maple N09°E 26.75' mrkd "1/16S BT"  
6" Balsam S88°E 9.7' do  
8" Balsam S07°E 28.7' do  
7" Balsam S54°W 11.3' do  
Set sq'd cedar post adjacent.  
E= 7901257.226 N= 199522.057

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

Signed by Stephan J. Szyszkoski Date 06/18/2014  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

