

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 32W	13
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/06/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Southeast 1/16 corner. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the position for the corner at the intersection of straight lines connecting opposite
1/16 corners. The position falls in an inaccessible location, adjacent to a pond in a large marsh.
Established two WITNESS CORNERS on the East 1/16 line, 726.14' north of the corner position, and
589.89' south of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witness corner north: Set 1"IDx32" I.pipe with 2"
alum. MDNR cap on the East 1/16 line 726.14' north
of the position for the corner. Set measuring nail
with MDNR tag in the side of:
12" Cedar S79°E 17.7' mrkd "WC BT"
14" Cedar S10°W 6.25' do
4" Cedar N77°W 11.2' do
5" Balsam N01°E 14.05' do
Set sq'd balsam post adjacent.
E= 7899714.246 N= 204159.489

Witness corner south: Set 1"IDx32" I.pipe with 2"
alum. MDNR cap on the East 1/16 line 589.89' south
of the position for the corner. Set measuring
nail with MDNR tag in the side of:
9" Maple N74°E 1.3' mrkd "WC BT"
3" Maple S22°E 13.05' do
7" Balsam S78°W 8.3' do
9" Cedar N77°W 22.75' do
Set sq'd cedar post adjacent.
E= 7899710.628 N= 203758.444

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0041: N= 210246.990 m. E= 7895426.989 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2013

For the Michigan Department of Natural Resources, Forest Resources Division

