

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 32W	14
	S 28 T 49N R 32W	9
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 08/07/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 28) South 1/16 corner between Sections 27 and 28. Not previously monumented.

(9-Sec. 28) East 1/16 corner, Section 28. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 28) Established the position for the corner midway and on the Section line between Section
corner 1307.12' south and Quarter corner 1307.12' north.

(9-Sec. 28) Established the position for the corner midway and on a straight line between Quarter
corner 1299.78' east and the intersection of 1/4 lines of Sec. 28 1299.78' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" Sugar S17°E 16.1' mrkd "1/16S BT"
9" Maple S69°W 19.55' do
10" Maple N69°W 28.4' do
9" Cherry N08°E 17.35' do
Set sq'd cedar post adjacent.
E= 7900109.926 N= 203928.989

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N38°W 17.85' mrkd "1/16S BT"
11" Sugar N45°E 19.8' do
5" Sugar S25°E 27.05' do
5" Spruce S37°W 20.95' do
Set sq'd cedar post adjacent.
E= 7899715.844 N= 204336.816

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0041: N= 210246.990 m. E= 7895426.989 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2013

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL LAND SURVEYORS, JAN. 2, 1971

