

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W	F9
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 32W	2
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 07/22/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F9) Quarter corner common to Sections 21 and 28. 1852 - Established by Deputy Guy H. Carleton
midway and on the Section line between Section corners 39.935 chains east and west. Set post. Fir
10" N25°W 13 links, Yellow Birch 18" S5°E 20 links.

(2-Sec. 28) East 1/16 corner between Sections 21 and 28. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F9) The original post and accessories were not recovered. Reestablished the position for the
corner midway and on the Section line between Section corners 2575.43' east and west, proportionate
to the original record. A blaze on a 26" Cedar signature tree dating at least to 1956, faces the
reestablished position. Distance west to 1852 line call "enter swamp 44.00" checks (4.065 ch. R
3.99 ch. M). Distance east to line call "stream 10 links 20.60" checks (19.335 ch. R, 19.50 ch. M).

(2) Established the position for the corner midway and on the Section line between Quarter corner
1287.72' west and Section corner 1287.72' east. The position falls in a creek and cannot be
monumented. Established a Witness Corner on the Section line 28.0' west of the corner position, 21'
west of the west bank of the creek, and on the west edge of an apparent seasonal flooding.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F9) Set 1"IDx30" I.pipe with 4" alum. MDNR cap made
firm in a mound of rock. Set measuring nail with
MDNR tag in the side of:

9" Maple N15°W 9.3' mrkd "1/4S NBT"
6" Balsam S42°E 2.75' do
26" Cedar S22°W 7.85' do
6" Spruce N83°W 21.55' do
Set sq'd cedar post adjacent.
E= 7899330.957 N= 205144.165

(2) Set 1"IDx32" I.pipe with 2" alum. MDNR cap
28.00' west of the corner position for a WITNESS
CORNER. Set measuring nail with MDNR tag in the
side of:

10" Cherry N33°W 29.8' mrkd "1/16S BT"
3" Sugar N68°W 23.8' do
5" B.Spruce S73°W 8.45' do
3" Balsam S50°W 9.95' do
Set sq'd cedar post adjacent. The monument leans
slightly easterly due to subsurface rock. The top
marks the corner position.

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)

Coord. Ref.=NGS PID RL0041: N= 210246.990 m. E= 7895426.989 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2013

For the Michigan Department of Natural Resources, Forest Resources Division

