LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

ror	ഹ	rners	าท

Baraga (County)	_ Located in:	Corner Code #								
1. Public Land Survey	T 49N R 32W T R	<u>B11</u>								
2. Property Controlling in Section	S T R S T R					•				
3. Miscellaneous Property in Sec.	S T R S T R		B	eaiste	of De	eds Sta	amp & I	File N	lumber	
4. Lot No. , Red 5. Private Claims	corded Plat		L	B C		E F	G H		J K	
ı, Stephan J. Szyszkoski , in			3	井		9_	1,0	二	-11-	_12_
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of				18	- - -17	16-	——————————————————————————————————————	-	-14	13
	orner points mentioned in lines 3, 4 and of Land Surveyors or by a Decreared, found as expressed below:		I	9	_20_	21-	27	<u></u>	_23	-24-
NOTE: Not more than 2 corner on this certificate.	ers, all in the same town and rang	e, may be recorded	10 11 12	30	_2 9 	—28- —33-		<u>-</u>	-26- -35-	25 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (B11) Quarter corner common to Sections 30 and 31. 1852 Established by Guy Carleton, Deputy Surveyor on the Section line between Section corners 40.00 chains east and 35.40 chains west. Set post. Sugar 10" N76W 14 links, Sugar 12" S04E 21 links. 1976 K.L.Sackett RLS remonumented the corner at the position of an old post found. Set 1"IDx36" I.pipe with 4" aluminum cap. 8" Sugar N50E 14.6', 6" Sugar N63W 27.6', 4" Sugar S16E 16.9'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (B11) Found and accepted the 1976 monument in good condition and at record bearing and distance from the 1976 witnesses. The Sugar NW is in good condition, the Sugar NE is dead and down with scribing visible, the Sugar SE was cut down to facilitate GPS observations this date. The monument is located 29.1 ft. north of a straight line between Section corner 2530.16' west and Section corner 2590.64' east. This position does not conform to the measurements given in the original record, but I note that previous surveys in this township have shown that the original measurements of record are often highly inaccurate.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B11) Fd. 1"ID I.pipe with 4" alum. MDNR cap.

Set measuring nail with MDNR tag in the side of:

10" Sugar N18E 16.7'

mrkd "1/4S NBT"

14" Sugar S55E 26.0'

do

14" Sugar N81W 23.0'

do

7" Sugar N59W 27.6' old marks (1976 NBT)

Squared post adjacent. Bearings magnetic.

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Surveyor's Michigan License No.

33986

Date

10/23/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities