

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 29 T 49N R 34W	11
	S 29 T 49N R 34W	15
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10/18/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11) Southwest 1/16 corner, Section 29. Not previously monumented.

(15) West 1/16 corner between Sections 29 and 32. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

(15) Established the position for the corner midway and on the Section line between Section corner 1311.89' west and Quarter corner 1311.89' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" J.Pine N23°E 22.55' mrkd "1/16S BT"
4" J.Pine S85°E 2.7' do
5" J.Pine S50°W 12.4' do
9" J.Pine N60°W 20.8' do
4"x4" treated wood post adjacent.
E=7878202.445 N=204373.364

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" J.Pine N27°W 39.65' mrkd "1/16S BT"
6" J.Pine North 25.15' do
6" J.Pine N43°E 46.25' do
6" J.Pine N59°E 61.7' do
4"x4" treated wood post adjacent.
E=7878192.190 N=203972.536

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

