

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 34W	15
	S 28 T 49N R 34W	13
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 12/10/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15) **West 1/16 corner between Sections 28 and 33.** 1975 - K.L.Sackett RLS recovered and accepted a 2" O.D.
iron pipe with 3 1/4" dia. brass cap stamped "1/8 corner", set by an unknown surveyor. 1975
witnesses: 7" J.Pine N48E 22.5', 7" J.Pine S89E 33.4'

(13) **Southeast 1/16 corner, Section 28.** Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15) Found the monument described in the 1975 record, stamped "28 SWSW|SESW 33 NWNW|NENW 1/8" in
good condition and at record bearing and distance from the 1975 J.Pine witness N48E 22.5', in good
condition with scribing plain. The monument is 9.25' north of a straight line between E11 and F11,
and is 20.46' west of the midpoint between same. Made new witnesses as described below.

(13) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Found 2" iron pipe with 3.25" brass cap. Set
measuring nail with MDNR tag in the side of:
8" J.Pine N52°E 22.9' old scribing (1975 BT)
4" Maple N22°E 44.25' mrkd "1/16S BT"
7" R.Pine N05°W 50.55' do
15" R.Pine S79°W 47.35' do
E=7879785.148 N=203931.918

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" J.Pine N10°W 22.85' mrkd "1/16S BT"
9" J.Pine S53°E 5.45' do
6" B.Spruce South 24.5' do
5" J.Pine N88°W 9.6' do
Set sq'd cedar post adjacent.
E=7880608.071 N=204312.034

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

