

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 28 T 49N R 34W SMC 11-15 north	_____
	S 28 T 49N R 34W SMC 11-15 south	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/24/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(SMC 11-15 north) Special Meander Corner on the North shore of the easterly-most arm of Big Lake
and on the West 1/16 line of Section 28, between Government Lots 2 and 4. Not previously
monumented.

(SMC 11-15 south) Special Meander Corner on the South shore of the easterly-most arm of Big Lake
and on the West 1/16 line of Section 28, between Government Lots 1 and 4. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC 11-15 north) Established the position for the corner at the intersection of a straight line
between monumented 1/16 corners #11 and #15 with the GLO meander of Big Lake as given in the
original U.S. Field Notes of this township, said meander having been adjusted using the Compass
Rule. The position for the corner falls 456.68' south of 1/16 corner #11 and 488.74' north of SMC
on south side of Lake.

(SMC 11-15 south) Established the position for the corner at the intersection of a straight line
between monumented 1/16 corners #11 and #15 with the GLO meander of Big Lake as given in the
original U.S. Field Notes of this township, said meander having been adjusted using the Compass
Rule. The position for the corner falls 372.33' north of 1/16 corner #15 and 488.74' south of SMC
on north side of Lake.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC 11-15 north) Set 1"IDx32" I.pipe with 4" alum.
MDNR cap. Set measuring nail with MDNR tag in the
side of:
12" R.Pine N01°E 15.45' mrkd "SMC BT"
4" Oak N73°E 13.05' do
5" Oak S09°E 17.7' do
4" Sugar N58°W 40.05' do
Set sq'd cedar post adjacent.
E= 7879788.916 N= 204045.324

(SMC 11-15 south) Set 1"IDx32" I.pipe with 4"
alum. MDNR cap. Set measuring nail with MDNR tag
in the side of:
7" J.Pine N82°W 70.55' mrkd "SMC BT"
9" J.Pine S76°W 26.9' do
4" J.Pine S07°W 36.45' do
9" R.Pine S09°E 69.85' do
Set sq'd cedar post adjacent.
E= 7879793.860 N= 204194.188

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/06/2013

For the Michigan Department of Natural Resources, Forest Resources Division

