

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern.

I, Stephan J. Szyszkoski, in a field survey on 09/14/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 34) East 1/16 corner between Section 34 T49N-R33W and Section 3 T48N-R33W. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 34) Established the position for the corner midway and on the Township line between Quarter corner 1330.90' west and Section corner 1330.90' east. The position for the corner falls in a wet and inaccessible area and the corner position proper was not monumented. Established two WITNESS CORNERS: 212.00' north of the corner position and on the East 1/16 line; and 337.00' west of the corner position and on the Township line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap 212.00' north of the corner as a W.C. Set measuring nail with MDNR tag in the side of: 6" B.Spruce S70°W 11.1' mrkd "WC BT" 12" Cedar N29°W 3.25' do 9" Cedar N08°E 15.3' do 5" B.Spruce N72°E 5.2' do Set sq'd cedar post adjacent. E= 7891746.431 N= 202156.025 (The W.C.)

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap 337.00' west of the corner as a W.C. Set measuring nail with MDNR tag in the side of: 10" Cedar N01°E 19.75' mrkd "WC BT" 5" B.Spruce N29°E 4.15' do 3" Balsam S44°W 11.6' do 14" Cedar N84°W 12.4' do Set sq'd cedar post adjacent. E= 7891642.974 N= 202094.151 (The W.C.)

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by [Signature] Date 10/27/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division