

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 16 09/01/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 34) Southwest 1/16 corner, Section 34. Found no record of prior monumentation.

(16-Sec. 36) East 1/16 corner between Sec. 36 T49N-R33W and Sec. 1 T48N-R33W. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 34) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the east and north being monumented. From the position thus established, I found a 1-1/4" iron pipe with mushroomed top, N57°E 18.4' distant, placed by persons unknown, and not accepted as marking the position for the corner.

(16-Sec. 36) Established the position for the corner midway and on the Township line between Township corner 1318.74' east and Quarter corner 1318.74' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar N01°W 4.35' mrkd "1/16S BT" 12" Sugar N40°E 34.85' do 11" Sugar S60°E 25.55' do 13" Sugar S31°W 9.1' do Set sq'd cedar post adjacent. E= 7890945.877 N= 202503.103

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Spruce N83°E 24.25' mrkd "1/16S BT" 5" Balsam S73°E 57.0' do 18" Cedar S47°E 32.1' do 7" Balsam S44°E 35.85' do Set sq'd cedar post adjacent. E= 7894960.563 N= 202025.511

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by [Signature] Date 10/27/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division