

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey T 49N R 33W J11
2. Property Controlling in Section S T R K11
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 08/27/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J11) Quarter corner common to Sections 26 and 35. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 40.115 chains east and west. Set post. Sugar 10" S43°W 34 links, Sugar 8" N65°E 14 links. 1941 - Notes of N.T.Thompson RLS state that he found the original BT Sugar 8" N65°E 14 links 'O.K. 18" ', set a spruce post at the 1/4 corner and made a new B.T. Sugar 5" N32°W 17 feet.

(K11) Corner common to Sections 25-26-35-36. 1852 - Established by Z.B.Searles, Deputy. Set post. Y.Birch 12" S26°E 10 links, Sugar 10" N47°W 33 links. 1941 - Notes of N.T.Thompson RLS state that he found one original BT, the Y.Birch 12" S26°E 10 links "O.K." and that it was then 22" diameter. He set a pipe for the corner and new BTs: Y.Birch S77°W 23.4', and Maple N37°W 26.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J11) Found a 1"ID I.pipe, projecting 18" a.g. at record bearing and distance from the original B.T. Sugar N65°E, now a well rotted stump, and at record bearing and distance from the 1941 NBT Sugar N32°W, in good condition, now 13" d.b.h. with blazes overgrown to the point of being not discernable. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(K11) Found a 1"ID I.pipe, projecting 18" a.g. at record bearing and distance from the rotted stump remains of the original BT Y.Birch 12" S26°E 10 links. Also recovered at substantial record bearing and distance were the rotting stump remains of the 1941 NBTs, the Y.Birch with lower blaze still visible. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J11) Found 1" ID I.pipe with mushroomed top. Set measuring nail with MDNR tag in the side of: 13" Sugar N27°W 17.25' (1941 NBT) mrkd "1/4S NBT" 18" Sugar N34°E 6.5' do 11" Sugar S82°E 15.45' do 10" Sugar S30°W 5.25' do Set sq'd cedar post adjacent. E= 7892969.706 N= 203663.940

(K11) Found 1"ID I.pipe, pinched top. Set measuring nail with MDNR tag in the side of: 12" Sugar N31°W 26.0' mrkd "S26 NBT" 9" Sugar N51°E 19.1' "S25 NBT" 14" Maple S07°W 14.6' "S35 NBT" 6" Sugar S60°W 13.9' "S35 NBT" Set sq'd cedar post adjacent. E= 7893772.325 N= 203649.476

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by [Signature] Surveyor's Michigan License No. 33986

Date 10/27/2015

For the Michigan Department of Natural Resources, Forest Resources Division

