

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 12 08/10/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 34) Center-South 1/16 corner, Section 34. Not previously monumented.

(9-Sec. 34) Center-East 1/16 corner, Section 34. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 34) Established the position for the corner midway and on a straight line between Quarter corner 1292.35' south and the Center of Section 34 1292.35' north.

(9-Sec. 34) Established the position for the corner midway and on a straight line between Quarter corner 1308.84' east and the Center of Section 34 1308.84' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar N32°E 24.1' mrkd "1/16S BT" 13" Sugar S58°E 2.7' do 7" Sugar S45°W 11.1' do 18" Sugar N73°W 8.3' do Set sq'd cedar post adjacent. E= 7891348.377 N= 202495.967
(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Sugar S25°W 17.7' mrkd "1/16S BT" 12" Sugar N68°W 16.6' do 10" Sugar N07°E 31.95' do 8" Ironwood N74°E 18.6' do The position falls 1.15' north of and on the northerly extension of the west edge of a 14"x14"x34" long block of rock, long axis N-S. Set sq'd cedar post adjacent. E= 7891755.289 N= 202878.850

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by [Signature] Date 10/27/2015
Surveyor's Michigan License No. 33986
For the Michigan Department of Natural Resources, Forest Resources Division