

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 20 T 50N R 33W _____ S 20 T 50N R 33W _____ S _____ T _____ R _____	D8 8
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 8 07/26/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D8) Center of Section 20. Not established in the original survey.

(8-Sec. 20) West 1/16 corner, Section 20. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D8) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.
The position for the corner falls in the roots of a 6" maple and leans slightly SE'ly. The top
center of the aluminum cap marks the corner position.

(8-Sec. 20) Established the corner midway and on a straight line between Quarter corner 1311.48' west
and Center of Section 20 1311.48' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Maple N11E 10.6' mrkd "C1/4 BT"
4" Maple S60E 2.2' do
6" Maple S75W 13.3' do
9" Maple N28W 12.7' do
Sq'd a 6" Maple, adjacent.
Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Maple N47E 35.6' mrkd "1/16S BT"
7" Maple S22W 10.3' do
6" Maple S52W 12.4' do
4" Maple N57W 15.8' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/24/2011

For the Michigan Department of Natural Resources, Forest Management Division



16755

16756